


32. Drain Tile Investigation – TNT Howard LLC – 5/16/25

Shown below are drain tile located on the property. Tile will be flagged prior to installation and repaired as required if damaged.



2025 Tile Map of Installation Since 2005

